



# Preliminary Information

## PIT5682 Sunroof Sunshade Will Not Latch

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018 - 2019	All	All	All	All
Chevrolet	Traverse	2018 - 2019	All	All	All	All
GMC	Acadia	2017 - 2019	All	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	Some customers may comment that the front sunroof sunshade will not latch in the closed position.
<b>Cause</b>	The sunroof sunshade catch on the sunroof housing may be broken.



**Correction:**

Replace the front sunroof sunshade catch with P/N 84691055.  
Do NOT replace the Sunroof Housing for this condition.

Parts Information

Description	Part Number	Quantity
RETAINER, SUN RF S/S FABRIC	84691055	1

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
6081928	Replace Sunshade Striker	0.3
<b>*This is a unique Labor Operation for Bulletin use only.</b>		

### Version History

Version	<b>1</b>
Modified	05/13/2019 - Created on



© 2019 General Motors. All Rights Reserved.